HDR SURVEYS
SURVEYS & VALUATIONS

Drone Roof Inspection

Photographic schedule

Sample property (address removed)

SAMPLE ONLY | Page selection of actual report

Client	Name removed
Date of inspection	October 2026
Date of drone survey	October 2026
Date of this schedule	November 2026
Our reference	Sample report
Surveyor	Helen du Rose AssocRICS, RICS Registered Valuer (RICS no. 1289682)
Images	26 numbered D01 to D26

SAMPLE ONLY

This is not the full schedule. It shows the cover and 4 images selected from a 28 page drone roof inspection. Client details have been removed.

This schedule records the images captured during the drone survey of the roof. The images are numbered and labelled for reference; the surveyor's findings, condition ratings and advice are given in the Level 3 Building Survey report for the property. Images are not to scale and are taken from the air at varying distances.

SAMPLE



D03

CHIMNEY STA

Chimney stack with a metal cowl; moss and cracking to the flaunching

SAMPLE ONLY | Page selection of actual report, not the full report



D09

MAIN ROOF

Cracked and slipped clay tiles to the main roof

SAMPLE ONLY | Page selection of actual report, not the full report



D11

MAIN ROOF

Lead lined valley with slipped tiles and moss

SAMPLE ONLY | Page selection of actual report, not the full report



D18

DORMER

Dormer cheek tiles have slipped

SAMPLE ONLY | Page selection of actual report, not the full report